

**PROFORMA FOR SAFE DRINKING WATER AND SANITARY  
CONDITION CERTIFICATE**

No. 252

Dated : 24.07.2026

It is Certified that an inspection team headed by **Mrs. Sunita K (Assistant Engineer)** from **Assistant Engineer PHE G.W.R. Sub Division Jagdalpur (C.G.)** inspected **EMRS Kodenar, bastanar** on **20.03.2026** date of inspection and on the basis of Water Test Report (attached) Receipt no. 215 dated 20.07.2026 of District Water Testing Laboratory (NABL) Jagdalpur, District-Bastar (C.G.) (PHED Lab) Certified that **EMRS Kodenar, bastanar**, has safe drinking water facilities for the Customer and members of staff of the institution .

The restaurant also maintaining the hygienic sanitation condition in the Restaurant building & the campus as per norms prescribed by the Central/State/U.T. Government .

**This certificate is valid till - March 2027**

**Note** :- **Parameter (NABL)** - Turbidity, Colour, Odour, pH, Total Alkalinity, Total Dissolved Solids, Chloride, Total Hardness, Calcium, Magnesium, Fluoride.

**Parameter (Non-NABL)** - Specific Conductivity, Iron.



(Sunita K)

**Assistant Engineer  
PHE G.W.R. Sub Division  
Jagdalpur Dist-Bastar (C.G.)**

To

**EMRS Kodenar  
Block-bastanar, District-Bastar (C.G.)**